



Connection offline

## Technical Service Bulletin

Transaction No.: **2079999/2**

91 Volume control cannot be operated, background lighting not working DTC U11B900  
Volume control no communication

Release date: Apr 13, 2026

## Condition

| Model(s)                                                                                                                                                                                       | Year(s) | VIN Range | Vehicle Specific Equipment                                          |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|---------------------------------------------------------------------|
| A5, S5 (FU), A6 Sportback e-tron, S6 Sportback e-tron (GH), Q5, Q5 Sportback e-tron, SQ5, SQ5 Sportback e-tron (GU), Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron (GF) | 2025    | All       | 005F – Information Electronics<br>Software:<br>4346<br>4347<br>4361 |

| REVISION HISTORY |            |                                |
|------------------|------------|--------------------------------|
| Revision         | Date       | Purpose                        |
| 2                | -          | Revised header (Added A6 (FN)) |
| 1                | 11/10/2025 | Initial publication            |

### Customer states:

The customer complains that the volume control is not working correctly. It is not possible to operate the volume control, and the background lighting is not working.

### Workshop findings:

The complaint can be reproduced.

The DTC **“U11B900 Volume control no communication, active/static”** is logged in the control unit for information electronics J794 (diagnostic address 005F).

## Technical Background

Software issue in volume control.

## Production Solution

Production change implemented in third quarter of 2025.

## Service

Update the vehicle software following directions in TSB 2079690, *00 Combined software update 03.10.00/C (28.13.01) KD2*.

## Warranty

|                          |                                                                                                                                                                                                             |           |                                    |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------------------|
| <b>Claim Type:</b>       | <ul style="list-style-type: none"> <li>If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>                                                         |           |                                    |
| <b>Service Number:</b>   | 9110                                                                                                                                                                                                        |           |                                    |
| <b>Damage Code:</b>      | KD02                                                                                                                                                                                                        |           |                                    |
| <b>Labor Operations:</b> | Software update, including connecting battery charger                                                                                                                                                       | 0151 0010 | See SRT with associated operations |
|                          | Fixed rate for software update, including all required preliminary and follow-up work (including bus sleep cycle, calibration drive, additional work and restarting software update if flashing is aborted) | 0151 0040 | 130 TU                             |
| <b>Claim Comment:</b>    | As per TSB 2079999/2                                                                                                                                                                                        |           |                                    |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

When performing the combined software update, time stamps are not required for billing under warranty. You are therefore permitted to work on other vehicles at the same time. The combined software update can also be performed by non-productive personnel.

## Additional Information

All part and service references provided in this TSB (**2079999**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.