

	Mitsubishi Motors North America, Inc. TECHNICAL SERVICE BULLETIN		
SUBJECT: CHECK ENGINE LIGHT ON - P050A STORED	No: TSB-26-13-002		
	Version: 1		
	Reason for change: NA		
	Date: April 15, 2026		

TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, General Managers, Service Managers, Service Advisors, Parts Managers, Technicians and Warranty Administrators

AFFECTED VEHICLES

Certain 2026 Outlanders with 4B40 Gen 2 engine

GROUP

13 – Fueling

CUSTOMER COMPLAINT

Check engine light (CEL) is illuminated on the instrument panel

PURPOSE

MMNA has received reports from the field of customer concern of the check engine light on, with P050A stored in the Engine Control Unit (ECU). If a CEL is present, ADAS (Advanced Driver Assistance Systems) may be restricted or disabled.

REMEDY

Do Not Replace Parts, MMNA is investigating the concern. We will share more information when it becomes available. In the interim, clearing the Diagnostic Trouble Code (DTC) is the recommendation.

Please contact Customer Connections via email to report vehicles with fault code P050A. Please provide customer name, last 8-digits of VIN, and TSB-26-13-002 in the subject line and send email to:

- North and Southern states KY, TN, MS, AL, GA, FL, WV, VA, NC, SC: Grafton Patten, Connections Specialist: grafton.patten@na.mitsubishi-motors.com
- West, and Southern states AZ, NM, KS, OK, TX, MO, AR, LA: Jessica Clink, Connections Specialist: jessica.clink@na.mitsubishi-motors.com

Warranty

Please follow the instructions in WB2026-007.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly perform diagnosis and repairs on Mitsubishi vehicles, using Mitsubishi Motors approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply that the described repairs are covered under warranty. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.