



Service Bulletin

Bulletin No.: PIT6514

Date: April, 2026

PRELIMINARY INFORMATION

Subject: BCM Setting DTC U013A

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade	2025 - 2026		All	All	All	All
Cadillac	Escalade ESV	2025 - 2026		All	All	All	All
Chevrolet	Suburban	2025 - 2026		All	All	All	All
Chevrolet	Tahoe	2025 - 2026		All	All	All	All
GMC	Yukon	2025 - 2026		All	All	All	All
GMC	Yukon XL	2025 - 2026		All	All	All	All

Involved Region or Country	Europe and Middle East
Additional Options (RPO)	UET
Condition	Dealers may find a U013A (Lost Communication with TTPM) set in the BCM during service. No warnings or customer concerns will be present. This is expected on Export vehicles not equipped with TTPM (RPO UET).
Cause	The causes of the condition may be software anomalies.

Correction

If DTC U013A is set in History, it should be ignored. There will be NO customer concerns or indication to the customer that the DTC is set. No further repairs should be performed to correct this DTC as it is set falsely.

Version	1
Modified	04/30/2026 - Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.