



Service Bulletin

Bulletin No.: PIP6118

Date: May, 2026

PRELIMINARY INFORMATION

Subject: SES MIL DTC P2002 3.0L LZ0 After OTA Update N25-251385

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2023		ALL	ALL	3.0 LZ0	ALL
GMC	Sierra 1500	2023		ALL	ALL	3.0 LZ0	ALL

Involved Region or Country	United States, Canada, Europe, Middle East, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, S. Korea, Philippines, Australia/New Zealand
Condition	Some customers may notice a SES MIL on after accepting an OTA (Over The Air) update N25251385. The dealer may find that DTC P2002 has set
Cause	The OTA may have induced the DTC due to a programming error.

Correction

Perform a code clear using GDS2 and return the vehicle to the customer. Once the DTC is cleared, the ECM will relearn the necessary diagnostic values and the condition will be resolved.

If DTC P2002 returns at a later date as a current DTC, proceed with the appropriate SI diagnostics as outlined in the published service information.

Version	1
Modified	05/21/26 - Created on

