

ATTENTION:

GENERAL MANAGER ☐

PARTS MANAGER ☐

CLAIMS PERSONNEL ☐

SERVICE MANAGER ☐

IMPORTANT - All
Service Personnel
Should Read and
Initial in the boxes
provided, right.

© 2026 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2020-24MY Legacy & Outback
2024MY Impreza
2020-24MY Crosstrek
2024MY Forester
2022-24MY Forester Wilderness
2019-24MY Ascent

NUMBER: 18-241-26

DATE: 05/19/26

SUBJECT: DTCs P0730, P0746, P0747, P0841, P0846, P0867,
P1867, P1894, and P2723 Service Manual Correction

INTRODUCTION:

This Service Bulletin announces a correction to the diagnostic procedures for certain CVT related DTCs, including P0730, P0746, P0747, P0841, P0846, P0867, P1867, P1894, and P2723. The 25 model year Service Manual includes enhanced troubleshooting steps. To avoid misdiagnosis, always refer to the 25 model year Service Manual for the vehicle being diagnosed when diagnosing the DTCs listed above. This correction will be incorporated into the Service Manual in the future.

SERVICE PROCEDURE / INFORMATION:

For all vehicles listed as applicable, follow the 2025 service manual for the model being serviced when diagnosing the following DTCs: P0730, P0746, P0747, P0841, P0846, P0867, P1867, P1894, and P2723.

If, during troubleshooting, you are advised to diagnose another code that is not listed, refer to the original service manual. Additionally, always verify wiring and pin locations against the original service manual to prevent misdiagnosis.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD
RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is
ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.