

Technical Service Bulletin (TSB)

Direct Voltage Transformer ECU Fault Code P0606-48

REFERENCE:	TSB: 08-227-26 GROUP: 08 - Electrical	Date:	May 30, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (MW) Jeep Compass 2022 - 2026 (JJ) Jeep Avenger This bulletin applies to vehicles equipped with 1.2L EB Turbo 3 Cyl MHEV Engine (Sales Code EJB).			MARKET APPLICABILITY: ☐ NA☐ MEA ☐ SA☐ IAP ☒ EE☐ CH NOTE: This bulletin applies to the Enlarged Europe market.	
CUSTOMER SYMPTOM:	Technicians may experience the following: Fault code P0606-48 in the direct voltage transformer ECU.				
CAUSE:	Direct voltage transformer ECU DC/DC software				

DISCUSSION:

This Information Only bulletin contains information helpful or useful for technicians in diagnosing. The presence of fault code P0606-48 in the direct voltage transformer ECU DC/DC does not cause any malfunction or lighting of a warning lamp on the instrument panel.

No repairs are to be made. Check that the fault code only appears in the direct voltage transformer ECU DC/DC. Do not confuse with P0606-49 in the front electric drive machine ECU (MCU (CMM_E)).

Do not replace parts if there is only this fault code in the direct voltage ECU DC/DC.

POLICY:

Information Only.