



Technical Journal

TITLE:

ECM-P04F000, Evap System, High Pressure Purge Line

REF NO:
TJ 34857.2.0

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States and Canada

PARTNER:
3 US 7510 Volvo Car USA

ISSUE DATE:
2019-10-17

STATUS DATE:
2019-10-21

FUNC GROUP:
2340

FUNC DESC:
Fuel tank, fuel lines, evaporator system

Page 1 of 3

“Right first time in Time”

Attachment

File Name	File Size
TJ 34857.jpg	0.0325 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	10	B4204T23					2019-9999		-	201835-999952
224	A2	B4204T27					2019-9999		-	201835-999952
224	BR	B1FPHEV					2019-9999		-	201850-999952
235	10	B4204T23					2018-9999		-	201717-999952
235	A2	B4204T27					2018-9999		-	201717-999952
235	AL	B4204T44					2018-9999		-	201717-999952
235	BA	B1APHEV					2018-2019		-	201717-201816
235	BR	B1FPHEV					2019-9999		-	201817-999952
236	10	B4204T23					2018-9999		-	201717-999952
236	A2	B4204T27					2018-9999		-	201717-999952
238	10	B4204T23					2018-9999		-	201717-999952
238	A2	B4204T27					2018-9999		-	201746-999952
238	AL	B4204T44					2018-9999		-	201717-999952
238	BA	B1APHEV					2018-9999		-	201816-999952
238	BR	B1FPHEV					2018-9999		-	201746-999952
246	10	B4204T23					2018-9999		-	201717-999952
246	A2	B4204T27					2018-9999		-	201717-999952



Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246	AL	B4204T44					2018-9999		-	201746-999952
246	BA	B1APHEV					2018-9999		-	201717-999952
246	BR	B1FPHEV					2018-9999		-	201717-999952
256	10	B4204T23					2018-9999		-	201717-999952
256	A2	B4204T27					2018-9999		-	201717-999952
256	BA	B1APHEV					2018-9999		-	201717-999952
256	BR	B1FPHEV					2018-9999		-	201717-999952

CSC Customer Symptom Codes

Code	Description
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

VST Operation Number

VST Operation Number	Description
36001-2	Diagnostic trouble codes read / reset / known Diagnostic trouble codes with VIDA
98731-2	Evap valve replace acc, to TJ34857

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ECM	P04F000	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

If check engine light is on and ECM-P04F000 is set, please follow advise under “service”.

SERVICE:

* Replace only evaporator pipe in position 27, see attachment TJ 34857, according to VIDA.
Check VIDA for the latest part number of the evaporator pipe.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:
VST OP Number: 98731-2 & 36001-2

VEHICLE REPORT:

* New improved part is planned in 2019Q4. No more reports are needed.

To view TJ attachment continue to next page. This TJ has one attachment.

TJ 34857

