



Preliminary Information

PIP5689B 3.0L LM2 Diesel Engine With Malfunction Indicator Lamp Illuminated With One Or More DTCs Set - P2B60, P1010, P226D and/or P24B0

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2020	All	All	3.0 LM2	All
GMC	Sierra 1500	2020	All	All	3.0 LM2	All

Involved Region or Country:	North America
Condition:	Malfunction Indicator Lamp Illuminated with DTCs P2B60, P1010, P226D and/or P24B0 set.
Cause:	There is a software anomaly in the engine calibration that can falsely set DTCs P226D, P24B0, P2B60 or P1010.

Correction:

Check to see if Service Update [N192282970](#): Service Update - ECM and Reductant Control Modules is open.

If Service Update [N192282970](#) is open, please perform it.

If there is an active P24B0, repair per Service Information.

If all of the above have been performed and any of the DTCs return refer to service information for diagnosis and repair.

Version History

Version	3
Modified	11/26/2019 - Created on. 12/12/2019 - Updated to add DTCs. 01/07/2020 - Updated to refer the technician to N192282970.

