



Preliminary Information

PIC6399 Diagnostic Tip - Service Keyless Start message with B1446 SYM13 Interior Keyless Entry Antenna 3 High Signal

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT5	2020	ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	A technician may find a Service Keyless Start message displayed . DTC B1446 SYM13 may be found relating to the Keyless Entry Antenna Rear Compartment
Cause	The T10E Keyless Entry Antenna - Rear Compartment may not be mounted in its bracket.

Correction:

Inspect the T10E Keyless Entry Antenna - Rear Compartment for being loose or having fallen out of the bracket.



T10E Keyless Entry Antenna - Rear Compartment

Version History

Version	1
Modified	01/28/2020 - Created on



© 2020 General Motors. All Rights Reserved.