



Bulletin No.: PIP5713
Published date: 03/9/2020

Preliminary Information

PIP5713 P16F3 Setting After Doing A Cylinder Deactivation Test Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2020	All	All	6.2L LT2	All

Involved Region or Country	North America
Condition	P16F3 setting after performing a cylinder deactivation test with GDS
Cause	Software anomaly

Correction:

Clear the codes when done with the test.

Note: Do not replace the ECM for this concern.

Warranty Information

Version History

Version	1
Modified	03/09/2020 - Created on

