

5/18/2016 MY 16 DS

GPOP - Issue Review System

Part Number: 68292756A\$

Part Description: 2016 DS ABS Module

Issue Description: Before replacing the ABS module for a wheel speed sensor fault(s) listed below, please call Brittany Potton at cell (248) 494-1087. If you don't receive response within 15 minutes, please continue with normal repair procedure.~

~
Possible wheel speed sensor faults: ~

C0030-02 Left Front Tone Wheel-General Signal Failure~

C0031-1D Left Front Wheel Speed Sensor-Circuit Current Out of Range~

C0031-2F Left Front Wheel Speed Sensor-Signal Erratic~

C0031-62 Left Front Wheel Speed Sensor-Signal Compare Failure~

~

C0033-02 Right Front Tone Wheel-General Signal Failure~

C0034-1D Right Front Wheel Speed Sensor-Circuit Current Out of Range~

C0034-2F Right Front Wheel Speed Sensor-Signal Erratic~

C0034-62 Right Front Wheel Speed Sensor-Signal Compare Failure~

~

C0036-02 Left Rear Tone Wheel-General Signal Failure~

C0037-1D Left Rear Wheel Speed Sensor-Circuit Current Out of Range~

C0037-2F Left Rear Wheel Speed Sensor-Signal Erratic~

C0037-62 Left Rear Wheel Speed Sensor-Signal Compare Failure~

~

C0039-02 Right Rear Tone Wheel-General Signal Failure~

C003A-1D Right Rear Wheel Speed Sensor-Circuit Current Out of Range~

C003A-2F Right Rear Wheel Speed Sensor-Signal Erratic~

C003A-62 Right Rear Wheel Speed Sensor-Signal Compare Failure~

~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
