

SSM 49269: 2021 Explorer/Aviator/Police Interceptor Utility - Flashing Powertrain Malfunction (Wrench) Indicator In Transport Mode With DTC P112A

Some 2021 Explorer/Aviator/Police Interceptor vehicles may exhibit a flashing powertrain malfunction (wrench) indicator while in transport mode with diagnostic trouble code (DTC) P112A stored in the powertrain control module (PCM). This may be due to excessive engine starts while the vehicle is in transport mode. To correct the condition, deactivate transport mode. Refer to Workshop Manual (WSM), Section 419-10 > General Procedures. Cycle the ignition to RUN. If the concern still exists, perform normal diagnostics in the Powertrain Control/Emissions Diagnosis (PC/ED) Manual.

Vehicles:

2021	Aviator (U611N) (TV)
2021	Explorer (U625N) (TW)

Symptom Code:

Global Customer Symptom Codes:

Category	Q1	Q2	Q3	Full Code
Driver Aides & Information				2****
Driver Aides & Information	Warning Indicators/Messages/Chimes			227***
Driver Aides & Information	Warning Indicators/Messages/Chimes	Electronic Throttle Control (Wrench Image)		2275**
Driver Aides & Information	Warning Indicators/Messages/Chimes	Electronic Throttle Control (Wrench Image)		227500
Driver Aides & Information	Warning Indicators/Messages/Chimes	Electronic Throttle Control (Wrench Image)	Flashes	227530
Driver Aides & Information	Warning Indicators/Messages/Chimes	Service Engine Soon (Engine Image)		227Q**
Driver Aides & Information	Warning Indicators/Messages/Chimes	Service Engine Soon (Engine Image)		227Q00
Driver Aides & Information	Warning Indicators/Messages/Chimes	Service Engine Soon (Engine Image)	Flashes	227Q30
Driver Aides & Information	Warning Indicators/Messages/Chimes	Not Listed		227Z**
Driver Aides & Information	Warning Indicators/Messages/Chimes	Not Listed		227Z00
Maintenance/ Pre-Delivery				9****
Maintenance/ Pre-Delivery	Pre-Delivery Check			991***
Maintenance/ Pre-Delivery	Pre-Delivery Check			9910**
Maintenance/ Pre-Delivery	Pre-Delivery Check			991000