



Preliminary Information

PIP5756 DTC P2101 Set In History Only

Proactive
Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT5	2020 - 2021	All	All	2.0 LSY	All

Involved Region or Country:	North America
Condition:	DTC P2101 set in history.
Cause:	Unknown complete published diagnostics for DTC P2101 in Service Information.

Correction

If you encounter a vehicle with DTC P2101 stored in history complete the published Service Information for this DTC.

Unless you're instructed through the diagnostic procedure in Service Information do not replace Throttle Body assembly for history DTC P2101.

Throttle Body Assemblies returned for warranty analysis have been tested and inspected with no trouble found.

If Service Information does not isolate the root cause for the history DTC P2101, clear the code and operate the vehicle under the conditions for running the DTC.

If DTC P2101 does not reset release the vehicle to the customer.

GM Engineering is aware of this concern and working toward a repair.

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
4087598	Complete published diagnostics for P2101 and clear DTC if diagnostic does not lead to a repair.	0.3 Hr.

Version History

Version	1
Modified	10/05/2020 - Created on.

