

SSM 49363 - 2017-2019 F-Super Duty - Intermittent No Crank With Or Without DTC P06E9

Some 2017-2019 F-Super Duty vehicles may experience an intermittent no crank condition. Diagnostic trouble code (DTC) P06E9 may also be set in the powertrain control module (PCM). This may be due to corrosion being present on the run start relay in the battery junction box (BJB). Inspect the run start relay for signs of corrosion, including along the terminal edges, prior to performing Workshop Manual (WSM) diagnostics. If no corrosion is found on the run start relay, refer to WSM, Section 303-06 to address this condition.

APPLICABLE VEHICLES

2017 - 2019 TRUCK: FE P558N SUPER DUTY