



Preliminary Information

PIT5831 Intermittent Malfunction Indicator Lamp (MIL) Illuminated - DTC P146F Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2020 - 2021	All	All	LIH	All
Chevrolet	Trailblazer (Vin M)	2021	All	All	LIH	All

Involved Region or Country	North America
Additional Options (RPO)	LIH
Condition	Some customers may comment that the MIL is illuminated. Upon a GDS2 scan check DTC P146F (EVAP Purge System Pressure Sensor Performance) may be set in the Engine Control Module (ECM).
Cause	There is a software anomaly that has been root caused to the use of the OnStar APP remote start function.

Correction:

This concern is very intermittent, vehicle may go weeks and/or hundreds of miles between occurrences.

No repairs should be completed at this time.

Please communicate to the customer that we apologize for this inconvenience and to limit the use of the Onstar Remote Start App for the time being.

Engineering is working on a permanent solution. As more information becomes available this PI will be updated or advanced to a bulletin.

Version History

Version	1
Modified	04/06/2021 - Created on.



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.