

## **SSM 50230 - 2019-2020 Edge/Nautilus – 2.0L EcoBoost - Illuminated MIL With DTCs P0137, P0141 And/Or P2096 – Built On Or Before 14-Oct-2020**

Some 2019-2020 Edge/Nautilus vehicles equipped with 2.0L EcoBoost engine and built on or before 14-Oct-2020 may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble codes (DTCs) P0137, P0141 and/or P2096. This may be due to an exhaust gas oxygen sensor seal. To correct the condition, install an updated oxygen sensor, part number K2GZ-9G444-D. Refer to Workshop Manual (WSM), Section 303-14A. For claiming, use casual part 9G444 and the applicable labor operations of Section 10 of the Service Labor Time Standards (SLTS) Manual.

### **APPLICABLE VEHICLES**

2019 - 2020 CAR: DQ CD539N EDGE

2019 - 2020 CAR: D9 U540N MKX

ERROR: syntaxerror  
OFFENDING COMMAND: --nostringval--

STACK:

```
(      ~      ~      ~      ~      6      N      f      ~      fi      fi      ~      b      "      '
)
(      ~      i      #      i      #      i      #      i      #      i      #      i      #      i      #      i      #      i      #      Z      <      D      a      D      a      D      a      D      a      D
)
(      cvt      „p      5      <      ...fpgm~      7      h      +glyph»]l      P      `      headłMy-      6hhea      >      k
)
-mark-
/sfnts
```