

Subject

4WD Inoperative, Lights Flashing on Dash

Market

USA

Service Category

Drivetrain

Section

Transfer/4wd/Awd

Applicability

2018-2022 Tacoma**APPLICABLE VEHICLES****2018-2022****Tacoma****CONDITION**

Water intrusion to the ADD actuator is currently being investigated as a cause of 4WD inoperative complaints. P17A0 and P17A4 DTCs may set for this condition but not always.

RECOMMENDATIONS

Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references