

9003584

03/29/2017

MY16 LA, LD, LX, WD, WK MY17 LD, RU, WD, WK

## **GPOP - Issue Review System**

**Part Number:** 05154726A\$, 05154743A\$, 05154744A\$, 05154727A\$, 05154730A\$, 05154731A\$, 05154732A\$, 68243433A\$, 68243432A\$, 68274990A\$, 68274991A\$, 68274992A\$, 68274993A\$, 68274994A\$, 68274995A\$, 68274996A\$, 68274997A\$, 68274998A\$, 68323540A\$, 68323541A\$, 68323542A\$, 68323543A\$, 68323544A\$, 68323545A\$, 68323546A\$, 68323547A\$, 68323548A\$, 05154831A\$, 05154832A\$, 05154833A\$, 05154834A\$, 68249218A\$, 68251877A\$, 68321633A\$, 68321636A\$, 68321637A\$, 68321638A\$, 68321639A\$, 68321640A\$, 68321641A\$, 68321642A\$, 68367340A\$, 68367341A\$, 05154838A\$, 68288305A\$, 68288308A\$

**Part Description:** Electric Power Steering Gear

**Issue Description:** If any of the following DTCs exist, it is okay to replace the steering gear: C2217-00, C15C1-00 (EPS Mechanical Performance) or C15DB-00 (Latch Active) otherwise perform the following;

1) Electrical, Communication or DTC (other then above) issue please contact:  
Terry Gavit @ cell (248) 882-6108 [terry.gavit@fcagroup.com](mailto:terry.gavit@fcagroup.com)  
Engineering is requesting a copy of Vehicle Scan Report (VSR) to be emailed to the above address.

2) Noise or Mechanical issue please contact: Ruth Delong @ cell (810) 569-0354.~

If you do not receive a return call within 15 minutes, proceed with the repair.~

Please be sure to attach a copy of the Vehicle Scan Report on the repair order.~

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~