



STAR ONLINE PUBLICATION



CHRYSLER

DODGE



Jeep



SRT

Case Number: S2108000149

Release Date: June 2021

Symptom/Vehicle Issue: DTC U0159-00, U015C-00, U0102-00, and/or U1070-00 Set In The BSCM

Discussion: The BSCM (Brake System Control Module) May have one or more of the following DTC's set: U0159-00, U015C-00, U0102-00, U1070-00. The BSCM may set these faults If some of the vehicles modules were not updated to the latest software level.

Repair: If the faults are either Active or Stored. Using WiTech, Ensure the following modules are updated to their latest software level.

BCM is updated to the latest SW Level

CVPAM/PAM is updated to the latest SW Level

CADM is updated to the latest SW Level

DTCM is updated to the latest SW Level

Verification: After the software updates are complete clear the DTC's. If one or more of the DTC's returns as Active. Follow the DTC flow chart for that DTC.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found