



STAR ONLINE PUBLICATION



Case Number: S2218000010

Release Date: June, 2022

Symptom/Vehicle Issue: Malfunction Indicator Lamp (MIL) Illumination, Diagnostic Trouble Code (DTC) P026B – Injection Timing Performance, Set.

Discussion: Some customers may experience a MIL illumination. Upon further investigation, a technician will find DTC P026B set in the Powertrain Control Module (PCM). There will be no other powertrain related DTCs set, or other drivability issues noted when the DTC sets.

If you receive a vehicle with this condition, please do not replace any parts at this time. The DTC is setting falsely. Engineering is currently developing a software update to correct the concern. Additional communication will be released once a fix is available.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found