

7/27/16

MY16 WK, WD

GPOP - Issue Review System

Part Number: 68313387A\$

Part Description: TPM Sensor

Issue Description: 2016 WK/WD vehicles only - Engineering is investigating a Tire Pressure Monitor (TPM) issue for TPM lamp ON and Active diagnostic trouble codes C1501-31, C1502-31, C1503-31, C1504-31. 2015 & 2016 TPM Sensors ARE NOT interchangeable.~

As part of normal diagnostics tool # 9936 TPM-RKE Analyzer can be used to wirelessly retrieve TPM sensor data and aid you in diagnosing. The tool filters data by year and body style. Be sure to update the tool to Software Version 16.01 and check for updates periodically. Vehicles and new TPM info is added several times a year. Updates are available through TechCONNECT home page; Service Tools & Equipment; Tire Pressure Monitor Tool; Software Downloads. ~

Prior to replacing any components on MY16 WK/WD vehicles, please contact Raja Charabuddi on cell (248) 202-7313 or Brian Malski on cell (248) 892-1514. If no response within 15 minutes, proceed with repair. ~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
