

|                      |                                                                                            |
|----------------------|--------------------------------------------------------------------------------------------|
| <b>Reference</b>     | SSM74093                                                                                   |
| <b>Models</b>        | Discovery Sport / L550<br>Range Rover Evoque / L538<br>Range Rover Velar / L560            |
| <b>Title</b>         | AJ20-P4 - Restricted Performance - P0191-85 Stored in the Powertrain Control Module (PCM). |
| <b>Category</b>      | Engine                                                                                     |
| <b>Last modified</b> | 03-Oct-2018 00:00:00                                                                       |
| <b>Symptom</b>       | 404000 Fuel System Concerns                                                                |

**Content****Issue:**

The customer reports reduced performance with P0191-85 observed in the PCM. This may or may not also illuminate the MIL. DTCs P168F-00, P2178-00, or P144C-00 may be stored also.

**Cause:**

An updated PCM calibration has now been released within Patthfinder and a seperate bulletin is due to be published shortly. Please note that AJ20-P4 High engine derivatives are not included within this SSM.

**Action:**

Update the Pwertrain Control Module in line with standard processes.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.