

Reference	SSM74092
Models	E-PACE / X540 F-PACE / X761 XE / X760
Title	AJ20-P4 - Restricted Performance - P0191-85 Stored in the Powertrain Control Module (PCM).
Category	Engine
Last modified	03-Oct-2018 00:00:00
Symptom	404000 Fuel System Concerns

Content**Issue:**

The customer reports reduced performance with P0191-85 observed in the PCM. This may or may not also illuminate the MIL. DTCs P168F-00, P2178-00, or P144C-00 may be stored also.

Cause:

An updated PCM calibration has now been released within Pathfinder and a separate bulletin is due to be published shortly. Please note that AJ20-P4 High engine derivatives are not included within this SSM.

Action:

Update the Powertrain Control Module in line with standard processes.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.