



Service Bulletin

Bulletin No.: PIE0503A

Date: February, 2019

ENGINEERING INFORMATION

Subject: Engineering Information – Reduced Engine Power, DTC P0299 Set

This PI has been revised to end the need for information from the field.
Please discard PIE0503.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore	2015	2019			Equipped with 1.4L Engine (RPO LUV)	Equipped with TRANSMISSION-AUTO 6 SPD, TRANSMISSION-MAN 6 SPD (RPOs MNK, MR5)
Cadillac	XT4	2019				Equipped with 2.0L Engine (RPO LSY)	Equipped with TRANSMISSION-AUTO 9 SPD (RPO M3H)
Chevrolet	Sonic	2015				Equipped with 1.4L Engine (RPO LUV)	TRANSMISSION-AUTO 6 SPD, TRANSMISSION-MAN 6 SPD (RPOs MNK, MR5)
	Trax						
	Equinox	2018				Equipped with 1.5L, 2.0L Engines (RPOs LYX, LTG)	Equipped with TRANSMISSION-AUTO 9 SPD (RPOs M3H, M3D)
	Silverado 1500 (New Model)	2019				Equipped with 2.7L Engine (RPO L3B)	Equipped with TRANSMISSION-AUTO 8 SPD (RPO MQE)
GMC	Terrain	2018				Equipped with 1.5L, 2.0L Engines (RPOs LYX, LTG)	Equipped with TRANSMISSION-AUTO 9 SPD (RPOs M3H, M3D)
	Sierra 1500 (New Model)	2019				Equipped with 2.7L Engine (RPO L3B)	Equipped with TRANSMISSION-AUTO 8 SPD (RPO MQE)

If you encounter a vehicle with the above condition, refer to Bulletin 18-NA-020 for further diagnosis.

Version	2
Modified	February 20, 2019 – Ended the need for information from the field.