



Preliminary Information

PIP5515 Repeat MIL On P2097

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2018	All	All	1.5L L3A	All

Involved Region or Country	North America
Condition	Repeat MIL On P2097
Cause	Under Investigation At This Time.

Correction:

Some customers may comment that the MIL has come on.
DTC P2097 may be set current or in history.
Confirm that the latest calibrations from 17058 have been installed.

- If the calibrations are current, perform the diagnostic in Service Information for the code.
- If the diagnostic for the code fails to isolate the cause of the concern, do not attempt repairs at this time.
- Clear codes and return the vehicle to the customer.
- Advise the customer that GM is aware of this concern and is working on a resolution.

Version History

Version	1

