

Classification:

Reference:

COPYRIGHT© NISSAN NORTH AMERICA, INC.
Date:

EC19-014

ITB19-006

March 4, 2019

INFINITI; MIL ON WITH DTC P219A AND/OR P219B STORED

APPLIED VEHICLES:

- 2015-2019 Q50 (V37)
- 2015-2018 Q50 Hybrid (V37)
- 2015-2019 QX60 (L50)
- 2015-2017 QX60 Hybrid (L50)
- 2015-2019 QX80 (Z62)

SERVICE INFORMATION

If the MIL is ON and DTC P219A (AIR FUEL RATIO IMBALANCE B1) and/or P219B (AIR FUEL RATIO IMBALANCE B2) is stored:

- DO NOT replace the Air Fuel Ratio (A/F) sensor.
- Refer to the applicable Electronic Service Manual (ESM) and follow the diagnostic procedure for DTC P219A and/or P219B.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 4, 2019	ITB19-006	Original bulletin published.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.