



Bulletin No.: PIP5662
Published date: 07/23/2019

Preliminary Information

PIP5662 SES Lamp P208E Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	LCF	2016 - 2019	All	All	3.0 5.2 IZ3 I1B	All

Involved Region or Country	North America
Condition	A vehicle may have a concern of a MIL illuminated with a P208E set in the DEF control module
Cause	Possible stuck DEF injector

Correction:

Flow the SI diagnostic for the P208E.

If the diagnostic leads to the DEF injector, replace the DEF injector and the DEF Supply Pump Filter Element

Place the supply pump filter element in a bag to be shipped back with the DEF injector.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4087058	DEF injector and suply pump filter element	1.3 HR
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	07/23/2019 - Created on

