

August 14, 2019

Version 6

MIL Comes On with DTC P0430 (Front Bank Catalyst System Efficiency Below Threshold [Bank 2])

This bulletin is replaced by S/B 19-072, *MIL Comes On with DTC P0430 or DTC P0430 with P030X, P219A, P219B (With Software Update)*

WARRANTY CLAIM INFORMATION

If you did the repair in service bulletin 17-036 on or before July 4, 2019 (RO date), use the information provided below.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1255C1	Update the PGM-FI software.	0.2 hr	03214	03217	17-036B	37805-RLV-315
B	Confirm 9 A/T software update only.	0.1 hr				

NOTE

Use the information below only if the 9 A/T software update was required.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1255C1	Update the PGM-FI software.	0.2 hr	03214	03217	17-036C	37805-RLV-315
B	Confirm 9 A/T software update only.	0.1 hr				
C	Do the 9 A/T software update.	0.1 hr				

Skill Level: Repair Technician

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.