



Technical Service Bulletin

91 Radar for ACC, DTC C110300 (symptom 791) - Repair Authorization

91 19 84 2056004/1 August 29, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2019	021089 - 999999	With Adaptive Cruise Assist

Condition

Customer states:

- The Adaptive Cruise Assist feature, along with other driver assistance systems is not working.

Workshop findings:

The following DTC may be stored in the control module for adaptive cruise control, J428 (address word 0013):

- **DTC C110300** (Adaptive cruise control sensor misadjusted) with symptom code 791.

Technical Background

Various parts have been replaced or recalibrated under warranty for the condition noted above, but no issues were identified with these parts. In an effort to gain information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing or recalibrating any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

1. Verify the condition.
2. If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC and diagnostic log to the TAC ticket.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All parts and service references provided in this TSB (2056004) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.