



Technical Service Bulletin

90 DTC B170AF1 or B200FF3 stored in the control module for driver assist systems after a software update

90 19 27 2056015/1 August 30, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, and Q8	2019 – 2020	All	Not Applicable

Condition

Customer states:

No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

After a software update for the control module for driver assist systems, J1121 (address word 00A5) one of the following DTCs is stored:

- **DTC B170AF1** (Coding Step 2 not carried out) static with symptom code 2117696.

Or

- **DTC B200FF3** (Internal malfunction static) with symptom code 221193.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

1. Execute the test plan "Check control unit configuration" and "Replace control unit" **without** replacing the control modules.
2. The DTCs can be cleared afterward.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9093		
Damage Code:	0039		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB # 2056015/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2056015) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.