

Subject		Market
Wi-Fi Intermittently Inoperative		USA
Service Category	Section	
Audio/Visual/Telematics	Cellular Communication	
Applicability		
2020 Tundra and Sequoia		

APPLICABLE VEHICLES

2020	Tundra	2020	Sequoia
------	--------	------	---------

CONDITION

Some 2020 model year Tundra and Sequoia vehicles may experience a B15DB or intermittent Wi-Fi inoperative (Wi-Fi icon greyed out). To simplify the diagnosis of the inoperative Wi-Fi, refer to the procedure below to prevent unnecessary parts replacement.

RECOMMENDATIONS

To restore the Wi-Fi operation perform one of the following:

- Turn the vehicle off for 3 hours minimum
- Remove the DCM fuse for 10 minutes
- Disconnect the battery for 10 minutes

LINK REFERENCES

This Tech Tip does not contain any link references