



Technical Journal

TITLE:

XC90 PHEV Low Pressure Fuel Pressure Sensor DTC ECM-P018C00REF NO:
TJ 32611.1.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-04-28STATUS DATE:
2017-05-03FUNC GROUP:
2349FUNC DESC:
Miscellaneous

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-2017		-	201526-201703

CSC Customer Symptom Codes

Code	Description
7G	Text window and warning symbol/Yellow symbol and text message
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ECM	P018C00	Intermittent

Text

**DESCRIPTION:**

If DTC ECM-P018C00 is set in vehicle, please follow advise under service.
New software released structure week 201703 to prevent this fault.

SERVICE:

Do not replace low pressure sensor.
Please perform a total upgrade in accordance with TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2349.