



Technical Journal

TITLE:

**Turtle in Driver's Information Module, DTC Engine Control Module
-U005500**REF NO:
TJ 32338.3.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-03-27STATUS DATE:
2017-03-30FUNC GROUP:
2621FUNC DESC:
Coolant pump, complete

Page 1 of 2

"Right first time in Time"

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-2017		-	201526-201716

CSC Customer Symptom Codes

Code	Description
AJ	Driving/Poor performance/lacks power

VST Operation Number

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ECM	U005500	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

If Engine Control Module-U005500 is set, follow advise under "Service".

SERVICE:

Do not replace any parts as this is identified as a software issue.

New software will be available week 16, 2017.

Until solution is available, the temporary solution is to reset the DTC and inform the customer that the software solution is on its way.

VEHICLE REPORT:

No more reports needed just for case building.