



Technical Journal

TITLE:

DIM message “BLIS system service required” and DTC SODREF NO:
TJ 30858.2.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-06-15STATUS DATE:
2017-06-21FUNC GROUP:
3872FUNC DESC:
Collision avoidance

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		0000001-0018031	201617-201708
235							2017-2017		0000001-0018643	201624-201708
236							2017-2017		0000001-0005496	201646-201708
238							2018-2018		0000001-0003398	201646-201708
256							2016-2017		0000001-0175152	201505-201708

CSC Customer Symptom Codes

Code	Description
XR	Blind spot information system (BLIS)/Does not work
IV	Text window and warning symbol/Text message

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

DESCRIPTION:

* Car type and chassis range changed

BLIS= Blind Spot Information system

DIM= Driver Information Module

SODL/SODR=Side Object Detection (Left/Right)

SOD=Side Object Detection

If a warning message “BLIS system service required” occur in DIM together with DTC SODR-U023292 or/and SODL-U023392, then follow the advice under Service.

SERVICE:

* In case of customer complaints for above symptom, upgrade the SOD software, please perform an upgrade of the software according to TJ 31543.

VEHICLE REPORT:

Only if this TJ does not solve the problem or if the symptom would occur after the chassis number ranges above. Use concern area “Vehicle Report” and sub concern area “Support Needed”, use function group 3872.