



SERVICE BULLETIN

Classification:	Reference:	Date:
EC17-034	NTB17-123	December 11, 2017

2018 ALTIMA AND SENTRA; DO NOT ERASE DTC P0315

APPLIED VEHICLES: 2018 Altima (L33)
2018 Sentra (B17)

APPLIED ENGINES: Altima QR25DE (4 cyl.)
Sentra MRA8DE (4 cyl. non-turbo)

SERVICE INFORMATION

If DTC P0315 is stored on an Applied Vehicle, do not erase it.

If DTC P0315 is stored, the description on the CONSULT-III plus screen will be listed as:
(TBD) Crankshaft Position System Variation Not Learned.

If you find DTC P0315 stored, please note the following:

- Do not erase the DTC.
- It will not turn ON the MIL.
- No diagnosis or repair is necessary.
- It will clear itself after a few trips with normal operation of the vehicle.

NOTE: If DTC P0315 is erased with C-III plus, the ECM will restart the learning pattern:

- The DTC may be stored again before the learning/driving pattern is complete.
- The MIL will not come ON.
- The DTC will clear itself after a few trips with normal operation of the vehicle.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.