



Technical Journal

TITLE:

Hybrid DTC BECM-P0CE100REF NO:
TJ 32903.2.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-10-13STATUS DATE:
2017-10-19FUNC GROUP:
3113FUNC DESC:
Battery, high voltage

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234	BC	B1BPHEV					2018-2018		0027016-0036478	201717-201739
238	BC	B1BPHEV					2018-2018		0015001-0035789	201717-201739
256	BC	B1BPHEV					2016-2018		0008280-0321806	201526-201739
256	BR	B1FPHEV					2018-2018		0190000-0321806	201717-201739

CSC Customer Symptom Codes

Code	Description
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

VST Operation Number

VST Operation Number	Description
36002-3	Software control module downloading

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BECM	P0CE100	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

DESCRIPTION:

*Vehicle profile updated.

The check engine light (CEL) may be illuminated without any other customer symptoms or the code BECM-P0CE100 is read out with VIDA. Please follow the advice under Service.

BECM = Battery Electronic Control Module

SERVICE:

* Perform an upgrade of the software according to TJ 31543.

VEHICLE REPORT:

* Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3113.