



Technical Journal

TITLE:

DTC BECM-P060A00 Internal Control Module Monitoring Processor Performance

REF NO:
TJ 33070.1.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2017-10-04STATUS DATE:
2017-10-09FUNC GROUP:
3113FUNC DESC:
Battery, high voltage

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246	BR	B1FPHEV					2018-2018		0000025-0017029	201717-201739
256	BC	B1BPHEV					2016-2018		0008280-0321806	201526-201739
256	BR	B1FPHEV					2018-2018		0008280-0321806	201717-201739

CSC Customer Symptom Codes

Code	Description
FB	Text window and warning symbol/Other problems

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
BECM	P060A00	Intermittent

Text

**DESCRIPTION:**

DTC BECM-P060A00 may appear when performing VIDA read out. If the DTC is present please follow step under Service.

Reported symptoms are:

- Error message in DIM

BECD = Battery Energy Control Module

DIM = Driver Information Module

SERVICE:

Perform an upgrade of the software according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3113.