

[Next Unread Message](#)**View Message**

Sent on 02 27 2014 **Expires on** 03 12 2014
From Parts and Service Division
Subject Request for Parts: 2004-2008 TL & TSX MIL On with DTC P2138

To: All Acura Service Managers/Consultants
From: Technical Research & Support Group
RE: Request for Parts: 2004-2008 TL & TSX MIL On with DTC P2138

This message is solely directed to Acura dealership personnel; please handle accordingly.
Print this iV message and provide a copy to the Shop Foreman and all Service Consultants.

Background

American Honda (AHM) is investigating certain 2004-2008 TLs & TSXs with a complaint of the Malfunction Indicator Lamp (MIL) on with the DTC P2138 (Accelerator Pedal Position Sensor A/B Incorrect Voltage Correlation) stored and poor engine performance. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting any further repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. MIL On with DTC P2138 stored
2. APP (Accelerator Pedal Position) sensors have not been replaced previously
3. Mileage must be over 80,000 miles

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.

© 2000–2014, American Honda Motor Co., Inc. All Rights Reserved.