



Preliminary Information

PIP5552 SES Light Comes On Setting A P0459 or P0443

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	3.6 LFY	All
Buick	LaCrosse	2017 - 2018	All	All	3.6 LGX	All
Buick	Regal	2018	All	All	3.6 LGX	All
Cadillac	ATS	2017 - 2018	All	All	3.6 LGX	All
Cadillac	CTS	2017 - 2018	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2018	All	All	3.6 LGX	All
Chevrolet	Camaro	2017 - 2018	All	All	3.6 LGX	All
Chevrolet	Colorado	2017 - 2018	ALI	All	3.6 LGZ	All
Chevrolet	Traverse	2018	All	All	3.6 LFY	All
GMC	Acadia	2017 - 2018	All	All	3.6 LGX	All
GMC	Canyon	2017 - 2018	All	All	3.6 LGZ	All
Involved Region or Country		North America				
Condition		Some customers may comment that the SES lamp is illuminated. During diagnosis technician may find DTC's P0459 (Evaporative Emission (EVAP) Purge Solenoid Valve Control Circuit High Voltage) or P0443 (Evaporative Emission (EVAP) Purge Solenoid Valve Control Circuit). These code(s) may be active or stored in history.				
Cause		GM Engineering is attempting to determine the root cause of the above condition.				

Correction:

Do not replace the purge valve or ECM for this condition. Clear the codes and release vehicle to customer.

NOTE: This PI will be update as soon as more information becomes available.

Version History

Version	1
Modified	

