



Service Bulletin

PRELIMINARY INFORMATION

Subject: DTC B125A.01 Set

Models: 2014 Chevrolet Impala LS
Equipped with Base Radio (RPO IO3)

Condition/Concern

Some technicians may find DTC B125A.01 set as current or in history. This DTC may be set falsely without an actual condition with the module.

This condition may be caused by a software anomaly.

Recommendation/Instructions

Clear the code. An updated software calibration will be released to address the false DTC in the near future. DO NOT replace the radio or the antenna amplifier for this condition.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4069929	Electrical Controls – Labor Only (To Clear DTC B125A.01)	0.2 hr

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION