

3/23/2016 MY15 JK

GPOP - Issue Review System

Part Number: 05149180A\$

Part Description: Oxygen sensor

Issue Before replacing the Right Downstream (1/2) O2 Sensor for a P0137 code on a 3.6L
Description: JK, please contact Jerry Tomlin at cell (248) 202-5329. If no response within 15 minutes, continue with repair.~

Engineering is investigating whether the sensors are getting contaminated with oil. For any other P-Code besides P0137, follow the applicable diagnostic procedure.~

~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.