

Reference	SSM72302
Models	F-TYPE / X152 XE / X760 XF / X260 XJ / X351
Title	B1412-96 is being flagged in the Gateway Module
Category	Electrical
Last modified	16-May-2018 00:00:00
Symptom	203000 Basic Electrical
Content	Note: This is only applicable to the following vehicles and models years XJ(X351) 13MY onwards F Type(X152) 14MY onwards XE(X760) 16MY onwards. XF(X260) 16MY onwards <u>Issue</u> B1412-96 being flagged in the Gateway Module <u>Cause</u> Under Investigation. <u>Action</u> False log of DTC 1412-96 in the Gateway Module and will not clear due to internal software issues. This will not affect the vehicle performance and is not visible to the customer. If DTC 1412-96 is identified: 1. Do not replaced the Gateway Module for this DTC. 2. Do not replace the Quiescent Relay Box for this DTC. SDD will be updated in due course. Technicians - Please rate this SSM and provide comments so that future communications can be improved. 1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern. 3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern. 5 = Excellent – All required information provided to resolve the customer concern.

