



Preliminary Information

PIT5631 False DTC U0020 Setting in the Video Processing Control Module

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UVI - Trailer Camera Package or UV2 - HD Surround Vision
Condition	It may be noticed when scanning the vehicle for DTC's there is a U0020 set current in the Video Processing Control Module (VPCM).
Cause	The VPCM will set a false U0020 DTC as a result of a software anomaly.

Correction:

NONE. This is a false DTC and it should be ignored. The DTC does not cause any vehicle symptoms and does not indicate that there are any issues with the vehicle.

Note: This PI will be converted into a bulletin when new information is available.

Version History

Version	1
Modified	09/14/2018 - Created

