



Service Bulletin

Bulletin No.: PIP6126

Date: September, 2026

PRELIMINARY INFORMATION

Subject: DTC P0494

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2026		All	All	2.0 LSY	All

Involved Region or Country	North America
Condition	DTC p0494 set as current or in history
Cause	Engineering is investigating root cause.

Correction

If DTC P0494 is stored (current or history) on one of these vehicles, Engineering is currently investigating root cause.

Clear DTC P0494.

In the meantime, please advise the customer they may continue to drive the vehicle. The PI will be updated or replaced with TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4083858 *	Clear DTC P0494	0.3 HR
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	09/25/2026 Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.