



Preliminary Information

PIP5471 Check Engine Light On With DTC P0181 after engine coolant heater usage.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2016	All	All	2.8 LWN	All
GMC	Canyon	2016	All	All	2.8 LWN	All
Involved Region or Country	North America					
Additional Options (RPO)	2.8 LWN					
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light on after using the engine coolant heater (block heater).					
Cause	Upon inspection technicians will find DTC P0181 set.					

Correction:

Complete the current SI diagnostic for any trouble codes or symptoms found. If after performing normal SI diagnostics and another root cause is not found, GM Engineering is aware of this concern and is working on a resolution.
This Preliminary Information will be updated when further information is available.

Version History

Version	1
Modified	