



Service Bulletin

PRELIMINARY INFORMATION

Subject: Engineering Information – Service 4WD Message Displayed, DTC C0392 Set

Models: 2014-2015 Chevrolet Silverado 1500

2015 Chevrolet Suburban, Tahoe

2014-2015 GMC Sierra 1500

2015 GMC Yukon, Yukon XL

Equipped with Transfer Case – Active, Two Speed, Push Button Control, Aluminum (NQH)

This PI has been revised to end the need for information from the field. Please discard PIE0342.

If you encounter a vehicle with this concern, please refer to the latest version of PIP5304 for field fix information.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION