

Classification:

EC17-018

Reference:

ITB17-046

Date:

August 8, 2017

DTC P0036 DIAGNOSTIC INFORMATION

APPLIED VEHICLES:

2016-2017 QX50 (J50)
 2016-2017 QX60 w/V6 Engine (L50)
 2016-2017 QX70 (S51)
 2016-2017 Q70 w/V6 or V8 Engine (Y51)

SERVICE INFORMATION

The Electronic Service Manual (ESM) information for DTC P0036 may be inaccurate or incomplete for the Applied Vehicles.

If an Applied Vehicle stores a DTC P0036, follow diagnostic procedures in the ESM for Bank 2 A/F Sensor Heater open or shorted.

DTC P0036 Diagnostic Conversion Table

Model	If P0036 is stored; Diagnose as this code in the ESM
2016 and 2017 QX50	P0051 and P0052
2016 and 2017 QX60 (V6)	
2016 and 2017 QX70	
2016 and 2017 Q70 (V6)	
2016 and 2017 Q70 (V8)	

NOTE: The ESMs will be updated at a later date.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.