

Classification:

Reference:

COPYRIGHT© NISSAN NORTH AMERICA, INC.
Date:

BR16-005

ITB16-047

November 28, 2016

INFINITI; DIAGNOSIS INFORMATION FOR ABS DTC C1130

APPLIED VEHICLES:	2012-2013 G37 Sedan (V36)	2014-2017 QX60 Hybrid (L50)
	2012-2013 G37 Coupe (V36)	2012 FX35 (S51)
	2014-2015 Q60 Coupe (V36)	2013 FX37 (S51)
	2017 Q60 Coupe (V37)	2012-2013 FX50 (S51)
	2012-2013 G37 Convertible (V36)	2014-2017 QX70 (S51)
	2014-2015 Q60 Convertible (V36)	2014-2017 Q50 (V37)
	2015 Q40 (V36)	2014-2017 Q50 Hybrid (V37)
	2012 EX35 (J50)	2012-2013 M37 (Y51)
	2013 EX37 (J50)	2012-2013 M56 (Y51)
	2014-2017 QX50 (J50)	2014-2017 Q70 (Y51)
	2013 JX35 (L50)	2014-2017 Q70 Hybrid (Y51)
	2014-2017 QX60 (L50)	

SERVICE INFORMATION

When diagnosing for DTC C1130 (ENGINE SIGNAL): ECM related DTCs (P-codes) must be diagnosed, repaired, and DTCs erased first.

- DTC C1130 is an ABS DTC that indicates an output signal of the ECM is not recognized.
- Absent or incorrect ECM signals, that are indicated by corresponding P-codes, may trigger C1130 in the ABS control unit.
- Some vehicle features that can be affected by absent or incorrect ECM signals are:
 - Forward Emergency Braking (FEB)
 - Intelligent Cruise Control (ICC)
 - VDC/ABS/TCS

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.