



SERVICE BULLETIN

Classification:

BR16-004

Reference:

NTB16-116

Date:

November 28, 2016

NISSAN; DIAGNOSIS INFORMATION FOR ABS DTC C1130

APPLIED VEHICLES:	2013-2017 Altima Sedan (L33)	2017 Titan (A61)
	2012 Altima Coupe (L32)	2012 Sentra (B16)
	2012-2014 Maxima (A35)	2013-2017 Sentra (B17)
	2016-2017 Maxima (A36)	2012-2013 Versa Hatchback (C11)
	2012-2014 Murano (Z51)	2012-2017 Versa Sedan (N17)
	2015-2017 Murano (Z52)	2014-2017 Versa Note (E12)
	2016-2017 Murano Hybrid (Z52)	2012-2017 Frontier (D40)
	2012 Pathfinder (R51)	2012-2017 Quest (E52)
	2013-2017 Pathfinder (R52)	2012-2017 Juke (F15)
	2014 Pathfinder Hybrid (R52)	2014-2017 NV Cargo/Passenger (F80)
	2012-2013 Rogue (S35)	2013-2017 NV200 (M20)
	2014-2015 Rogue Select (S35)	2014-2017 Taxi
	2014-2017 Rogue (T32)	2012-2015 Armada (TA60)
	2017 Rogue Hybrid (T32)	2017 Armada (Y62)
	2012-2015 Titan (A60)	2012-2017 370Z (Z34)
	2016-2017 Titan XD (A61)	

SERVICE INFORMATION

When diagnosing for DTC C1130 (ENGINE SIGNAL): ECM related DTCs (P-codes) must be diagnosed, repaired, and DTCs erased first.

- DTC C1130 is an ABS DTC that indicates an output signal of the ECM is not recognized.
- Absent or incorrect ECM signals, that are indicated by corresponding P-codes, may trigger C1130 in the ABS control unit.
- Some vehicle features that can be affected by absent or incorrect ECM signals are:
 - Forward Emergency Braking (FEB)
 - Intelligent Cruise Control (ICC)
 - VDC/ABS/TCS

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.