

Auto High Beam Problem Message with DTC U0423-68?

AFFECTED VEHICLES

2017 CR-V with Honda Sensing™

Are you seeing an **Auto High Beam Problem** message on the driver information interface with DTC U0423-68 (gauge control module malfunction)? We're aware of this issue and have it under investigation.

We suspect the left- and right-side BSI radar units may be the culprit, and we've even replaced them with some success toward resolving this issue. But because it's possible for this DTC to be triggered by other B-CAN control units, we can't draw any firm conclusions yet.

Until we can find the root cause and come up with a solution, for now, try replacing the BSI radar units and be sure to notify Tech Line of your results. When we have a solution for this issue, we'll let you know.